
National Criminal Justice Reference Service

ncjrs

This microfiche was produced from documents received for inclusion in the NCJRS data base. Since NCJRS cannot exercise control over the physical condition of the documents submitted, the individual frame quality will vary. The resolution chart on this frame may be used to evaluate the document quality.



MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

Microfilming procedures used to create this fiche comply with the standards set forth in 41CFR 101-11.504.

Points of view or opinions stated in this document are those of the author(s) and do not represent the official position or policies of the U. S. Department of Justice.

National Institute of Justice United States Department of Listice Washington, D.C. 20531 12/30/82

ANNUAL

MF.I

JAIL INSPECTION REPORT



8581

1977

ROBERT F. BENNETT

Governor

JAMES J. MARQUEZ
Acting Secretary of Corrections

U.S. Department of Justice National Institute of Justice

This document has been reproduced exactly as received from the person or organization originating it. Points of view or opinions stated in this document are those of the authors and do not necessarily represent the official position or policies of the National Institute of Justice.

Permission to reproduce this ocyvighted material has been granted by Kansas Department of Corrections

to the National Criminal Justice Reference Service (NCJRS).

Further reproduction outside of the NCJRS system requires permis sion of the copyright owner.

Printed by:
Kansas State Industrial Reformatory
Printing Department

KANSAS DEPARTMENT OF CORRECTIONS Topeka, Kansas

JIM J. MARQUEZ Acting Secretary of Corrections

Honorable Robert F. Bennett Governor of the State of Kansas 2nd Floor, State Capitol Building Topeka, Kansas 66612

Dear Governor Bennett:

Submitted with this letter is the 1977 Annual Report for the Kansas Jail System. I trust that the information contained herein will be of benefit to you and your staff. The Department of Corrections feels that . progress noted in this report serves as a measure of any improvement in upgrading the jails in Kansas.

I would, at your convenience, welcome the opportunity to discuss with you the contents of this report.

Since ely,

JIM J. MARQUEZ
Acting Secretary of Corrections

TABLE OF CONTENTS

PAG	<u> </u>	10.
INTRODUCTION	1	
DEFINITION OF TERMS	3	
JAIL INSPECTION ACTIVITIES	4	
FACILITIES THAT MEET THE KANSAS ADVISORY JAIL STANDARDS AND PROCEDURES	5	
FACILITIES NO LONGER IN USE	6	
DEFICIENCIES BY COUNTY (JAILS)	7	
Allen County Jail	8 8 8 9 9 10 11 11 12 13 14 15 15 16 16 17 7 17 18 19 19 20 20 20 21 22 23	
Kearny County Jail Kingman County Jail Labette County Jail	·24 ·24 ·25 ·27	
Linn County Jail Linn County Jail McPherson County Jail Marion County Jail	·27 ·28	

TABLE OF CONTENTS (Continued)

	PAGE N
DEFICIENCIES BY COUNTY (JAILS)	
(Continued)	
Meade County Jail	29
Miami County Jail	29
Mitchell County Jail	30
Montgomery County Jail Morris County Jail	30
Morton County Jail	30
Neosho County Jail	31
Ness County Jail	
Norton County Jail	
Osage County Jail	34
Osborne County Jail	35
Ottawa County Jail	35
Pawnee County Jail	36
Pottawatomie County Jail	36
Republic County Jail	36
Rice County Jail	37
Rooks County Jail	
Russell County Jail	
Saline County Jail	
Scott County Jail	
Sedgwick County Jail	39
Seward County Jail	40
Shawnee County Jail	40
Smith County Jail	41
Stanton County Jail	41
Stevens County Jail	42
Sumner County Jail	
Wabaunsee County JailWashington County Jail	
Wilson County Jail	
Wyandotte County Jail	44
wyandotte county darrantees	
EFICIENCIES BY COUNTY (LOCKUPS)	46
Horton City Lockup (Brown County)	47
Horton City Lockup (Brown County)Augusta City Lockup (Butler County)	47
Baxter Springs City Lockup (Cherokee County)	48
Columbus City Lockup (Cherokee County)	48
Pittsburg City Lockup (Crawford County)	49
Parsons City Lockup (Labette County)	49
Oakley City Lockup (Logan County)	50
Chanute City Lockup (Neosho County)	50
Russell City Lockup (Russell County)	51
UMMARY	F0
·UIIIIAK I	52

TT

INTRODUCTION

As enumerated in K.S.A. 75-5228, the Secretary of Corrections is given three major responsibilities in performing the jail inspection function:

- (1) The promulgation of advisory standards relating to the safety and sanitation of correctional and detention facilities.
- (2) The periodic inspection of correctional and detention facilities.
- (3) The presentation of evidence to local officials and judicial personnel that a particular facility within their jurisdiction needs major improvement or should be closed.

The program responsibility entails on-site inspection of jails, including such basic areas as administration, facility construction, personnel, housekeeping, food service, medical care, emergency procedures, sanitation, safety, counseling, recreation, and programs. The program staff also investigates complaints referred by the Governor's Office, the Attorney General's Office, and others, concerning the operation of jails and/or the treatment of prisoners.

It is evident that detention facilities throughout the state have been neglected for years. Not only are facilities old and antiquated, but Administrators' attitudes have not reflected the new concepts of rehabilitation and humane housing and treatment. Thought should be given to the fact that the jails of the state house many persons who are but charged with crimes and awaiting the completion of the judicial process. Those convicted and serving time in the jails are in need of safe and adequate facilities and activities which will reflect positively upon their behavior when they are eventually released back into the communities.

In this age of recognized human rights, more and more people are becoming aware of the right of the confined and seeking the assurance those rights are respected. State and federal courts throughout the nation are hearing cases regarding alleged "cruel and unusual punishment" because of the deplorable conditions of city, county and state detention/correctional facilities. In some cases, judgements have been rendered against the Administrators of the facilities. With the changing public and judicial attitudes impacting on the environment of local detention operations, it is anticipated that rapid change for the improvement of detention facilities and programs is inevitable.

DEFINITION OF TERMS

JAIL	A facility operated by a unit of local govern- ment for the physical detention and correction of persons charged with, or convicted of, criminal offenses for a period of one year or less.
LOCKUP	A facility operated by a unit of local govern- ment for the physical detention of persons charged with, or convicted of, criminal offenses for a period of seventy-two hours or less.
HOLDING FACILITY	A facility operated by a unit of local govern- ment for the temporary physical detention of persons awaiting processing, booking, appearing before court, or discharged.
CAPACITY	The number of bed space presently available.
RECOMMENDED CAPACITY	The bed space that should be available using a formula of fifty-two square feet of cell space per bed.
URGENT	A situation, or hazard, which presents an immedi- ate threat to the health and safety of the in- mates or employees, or the potential for escape.
NECESSARY	A situation, or hazard, which presents a potential threat to the health and safety of the inmates or employees if they are continually exposed to the situation over a prolonged period.
DESIRABLE	A condition which does not present an immediate or potential threat to the health and safety of the inmates or employees; but, if changed, would improve the habitability of the facility or the staff's ability to manage the facility.

JAIL INSPECTION ACTIVITIES

During the calendar year 1977, the Jail Inspection Staff was involved in forty-five joint inspections with the State Fire Marshal's Office and the State Department of Health and Environment. The Staff also investigated thirty-three complaints concerning the operation of jails and the treatment of inmates; attended forty-eight meetings with district judges, commissioners, attorneys, and architects for the purpose of planning new facilities or renovating existing ones; and inspected one-hundred and thirty-five detention facilities.

These inspections indicated that eighteen of these facilities were not being used for detention purposes. Of the one-hundred and eighteen operational facilities, eighty-eight are jails, nineteen are lockups, and eleven are holding facilities.

Л

- 3 -

FACILITIES

THAT MEET THE

KANSAS ADVISORY JAIL STANDARDS AND PROCEDURES

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16.	Bourbon County - Fort Scott	
18. 19. 20. 21. 22. 23. 24. 25. 26. 27.	Atchison)))))
28. 29. 30. 31. 32. 33. 34. 35. 36. 37.	Hoisington	ng ng ng ng ng ng

<u>FACILITIES</u>

NO LONGER IN USE

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13.	Chase County Commanche County Gove County Gray County Hamilton County Haskell County Marshall County Nemaha County Rawlins County Rush County Sheridan County Trego County Wichita County	Jail Jail Jail Jail Jail Jail Jail Jail
15. 16. 17. 18.	Arkansas City	Locku) Locku)

- 6 -

DEFICIENCIES BY COUNTY (JAILS)

					PRIORITY C CORRECTIVE ACTION		Æ	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
ALLEN COUNTY JAIL	1960	12	12	7	(1) No visual supervision of prisoners at least every 60 minutes.**(2) No around-the-clock awake and alert supervision.**	Х	Х	
ANDERSON COUNTY JAIL*	1925	26	9	1	 Inadequate administrative space.** Cell areas do not maintain 52 sq. ft. per prisoner.** Does not comply with State Fire Marshal's regulations.** Electrical fixtures are within prisoners reach.** No intercom system between jail office and cell block areas.** Inadequate ventilation.** Inadequate plumbing.** No standard inmate clothing issued.** Three meals per day, or the equivalent, are not provided.** Locking system needs repair.** 	X X	X X X X	Х
ATCHISON COUNTY JAIL*	1941	26	14	5	 (1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) Stairway will not accommodate an ambulance cot.** 		X X	Х

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	e.		П	AILY NO		COF	ORITY RRECTIV	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
ATCHISON COUNTY JAIL (Continued)					(4) No exercise area.** (5) Does not comply with State Fire Marshal's regulations.**	Х		Х
					(6) Wooden bunks being used.**(7) Drop cords accessible to prisoners.**(8) Electrical fixtures are within prisoners reach.**	X X	Х	
					(9) No emergency electrical power.** (10) No intercom system between jail office and cell block areas.**		X X	
					(11) Inadequate ventilation.** (12) Furnishings and fixtures in need of repair.** (13) Painted surfaces need repainting.** (14) Floor drains need flushing.** (15) Overall sanitation needs to be improved.**		X X	X X X
BARBER COUNTY JAIL	1957	7	5	1	(1) Cell areas do not maintain 52 sq. ft. per prisoner.** (2) No exercise area.**		Х	Х
BARTON COUNTY JAIL*	1953	62	34	18	(1) Cell areas do not maintain 52 sq. ft. per prisoner.** (2) No exercise area.		Х	Х
					(2) No exercise area. (3) Does not comply with State Fire Marshal's regulations.** (4) No emergency electrical power.**	Х	Х	۸

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 9

PRIORITY OF CORRECTIVE ACTION DATE CONSTRUCTED CAPACITY **DEFICIENCIES** NAME OF FACILITY BARTON COUNTY Painted surfaces need repainting. Doors on unoccupied cells are not kept JAIL (Continued) BROWN COUNTY 1924 15 10 (1) Cell areas do not maintain 52 sq. ft. per prisoner.** JAIL* No exercise area.** (3) Does not comply with State Fire Marshal's Χ regulations.** Wooden tables and benches being used in cell Χ block areas.** (5) Tables and benches not securely fastened to wall or floor.** Inadequate lighting in cell block areas.**
No emergency electrical power.** (8) No intercom system between jail office and cell block areas.** Inadequate ventilation.** (10) No standard inmate clothing issued.** CHEROKEE COUNTY 1950 14 Inadequate administrative space.**
No floor drains in cell block areas.** 14 JAIL* No exercise area.** Does not comply with State Fire Marshal's regulations.** (5) No intercom system between jail office and

cell block areas.**

- 10 -

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	A		А	AILY N		COF	ORITY RRECTIV ACTION	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
CHEROKEE COUNTY JAIL (Continued)					(6) Heating units inadequate to maintain a minimum of 68 degrees.** (7) Inadequate ventilation.** (8) No standard inmate clothing issued.** (9) Security equipment is in need of repair.**	X X	Х	X
CHEYENNE COUNTY JAIL*	1887	9	9	1	(1) Inadequate administrative space. (2) No security or insect screens on windows.** (3) No floor drains in cell block areas.** (4) No exercise area.** (5) Does not comply with State Fire Marshal's regulations.** (6) Electrical fixtures are within prisoners reach.** (7) No emergency electrical power.** (8) No intercom system between jail office and cell block areas.** (9) Inadequate ventilation.** (10) No standard inmate clothing issued.** (11) Tables and benches not securely fastened to wall or floor.**	X	X X X X	X X
CLARK COUNTY JAIL*	1950	5	3	1	(1) Inadequate administrative space.** (2) No exercise area.** (3) Does not provide adequate separation of prisoners.**		X X	Х

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	Ð		А	AILY ON		COF	ORITY RRECTIV	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
CLARK COUNTY JAIL (Continued)					 (4) No intercom system between jail office and cell block areas.** (5) No emergency electrical power.** (6) No standard inmate clothing issued.** (7) No around-the-clock awake and alert supervision.** (8) No visual supervision of prisoners at least every 60 minutes.** (9) No written emergency procedures.** 	X X X	X X	Х
CLAY COUNTY JAIL*	1903	12	9	4	 Inadequate administrative space.** Cell areas do not maintain 52 sq. ft. per prisoner.** No insect screens on windows.** Stairway will not accommodate an ambulance cot.** Does not comply with State Fire Marshal's regulations.** No floor drains in cell block areas.** No holding cell for the purpose of processing prisoners. Electrical fixtures are within prisoners reach.** No emergency electrical power.** No intercom system between jail office and cell block areas.** 	X	X X X	X X X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 12 -

	Ð.		A	N N		COF	ORITY RRECTIV ACTION	√E
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
CLAY COUNTY JAIL (Continued)					 (12) Inadequate ventilation.** (13) Inadequate plumbing.** (14) Plumbing fixtures are not of the type designed for jail use.** (15) Does not provide adequate containers in the cell block areas for disposal of solid waste.** (16) No visual supervision of prisoners at least every 60 minutes.** (17) Wooden tables and benches being used in cell block areas.** (18) Tables and benches not securely fastened to wall or floor.** 	Х	X X X	Х
CLOUD COUNTY JAIL*	1933	26	10	14	(1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No security screens on windows.** (4) No floor drains in cell block areas.** (5) No exercise area.** (6) Does not comply with State Fire Marshal's regulations.** (7) Electrical fixtures are within prisoners reach.** (8) Inadequate exterior lighting.** (9) No intercom system between jail office and cell block areas.** (10) Inadequate ventilation.**	X X	X X X	X X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	-D		А	NO N		COF	ORITY RRECTIV	/E
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
CLOUD COUNTY JAIL (Continued)					(11) No standard inmate clothing issued.** (12) No visual supervision of prisoners at least every 60 minutes.** (13) No around-the-clock awake and alert supervision.** (14) Does not provide adequate separation of prisoners.**	X X	Х	Х
COFFEY COUNTY JAIL*	1934	28	17	1	 Inadequate administrative space.** Cell areas do not maintain 52 sq. ft. per prisoner** No security or insect screens on windows.** Stairway will not accommodate an ambulance cot.** No floor drains in cell block areas.** No exercise area.** Does not comply with State Fire Marshal's regulations. Electrical fixtures are within prisoners reach.** No intercom system between jail office and cell block areas.** Inadequate ventilation.** Inadequate plumbing.** No standard inmate clothing issued.** Steam heat radiators are accessible to prisoners.** 	X	X X X X	X X X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.

** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 14 -

	a		G.	AILY ON		CO	ORITY RRECTIV ACTION	٧E
NAME OF FACILITY	DATE	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
COFFEY COUNTY JAIL (Continued)					(14) Window glass accessible to prisoners.** (15) No around-the-clock awake and alert super- vision.**	Х	Х	
COWLEY COUNTY JAIL	1960	42	42	20	(1) No intercom system between jail office and cell block areas.** (2) No standard inmate clothing issued.**		Х	Х
CRAWFORD COUNTY JAIL	1925	15	15	10	(1) No around-the-clock awake and alert supervision.**(2) No visual supervision of prisoners at least every 60 minutes.**	X		
DECATUR COUNTY JAIL*	1926	3	3	1	(1) Inadequate administrative space.** (2) No security or insect screens on windows.** (3) No exercise area.** (4) Does not comply with State Fire Marshal's regulations.**	Х	X X	X
					 (5) Inadequate ventilation.** (6) Plumbing fixtures are not of the type designed for jail use.** (7) No standard inmate clothing issued.** (8) Bunks, tables, and benches not securely fastened to wall or floor.** 		X X	X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.

** This deficiency existed in previous inspection reports but no corrective action has been taken.

	Œ		А	AILY ON		COF	ORITY RRECTIV	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
DICKINSON COUNTY JAIL*	1956	35	35	8	(1) Cell areas do not maintain 52 sq. ft. per prisoner.** (2) No exercise area.** (3) Does not comply with State Fire Marshal's regulations.** (4) No emergency electrical power.** (5) Heating units inadequate to maintain a minimum of 68 degrees.** (6) Inadequate ventilation.** (7) Painted surfaces need repainting.**	X	X X	X
DONIPHAN COUNTY JAIL	1957	13	13	3	 (1) No exercise area.** (2) No emergency electrical power.** (3) No intercom system between jail office and cell block areas.** (4) Inadequate ventilation.** (5) No standard inmate clothing issued.** (6) Painted surfaces need repainting. 		X X	X X X
EDWARDS COUNTY JAIL*	1928	11	11	2	(1) No insect screens on windows.** (2) No emergency electrical power.** (3) Bunks not securely fastened to wall or floor.		X X X	b

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.

** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 16 -

JAIL*

PRIORITY OF CORRECTIVE AVERAGE DAILY POPULATION ACTION DATE CONSTRUCTED CAPACITY NAME OF FACILITY DEFICIENCIES ELK COUNTY JAIL 1960 10 10 (1) No around-the-clock awake and alert supervision.** ELLSWORTH COUNTY 17 (1) Inadequate administrative space.**(2) Cell areas do not maintain 52 sq. ft. per 1910 12 2 JAIL* prisoner.** No floor drains in cell block areas.**
Does not comply with State Fire Marshal's regulations.** Inadequate lighting in cell block areas.** No emergency electrical power.** No intercom system between jail office and cell block areas.** Inadequate ventilation.**
Inadequate plumbing.**
No standard inmate clothing issued.**
Painted surfaces need repainting. (12) Does not provide two sets of keys for security area.** (13) Security equipment is in need of repair. (14) No visual supervision of prisoners at least every 60 minutes.** FINNEY COUNTY 1920 34 15 Inadequate administrative space.**

prisoner.**

- 17 -

(2) Cell areas do not maintain 52 sq. ft. per

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	Œ		a	AILY			PRIORITY OF CORRECTIVE ACTION		
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE	
FINNEY COUNTY JAIL (Continued)					 (3) No floor drains in cell block areas.** (4) No exercise area.** (5) Does not comply with State Fire Marshal's regulations.** (6) Does not provide adequate separation of prisoners.** (7) Inadequate lighting in cell block areas.** (8) No emergency electrical power.** (9) No intercom system between jail office and cell block areas.** (10) Three meals per day, or the equivalent, are not provided.** (11) No holding cell for the purpose of processing prisoners.** (12) Bunks, tables and benches not securely fastened to wall or floor.** (13) No around-the-clock awake and alert supervision.** (14) No visual supervision of prisoners at least every 60 minutes.** 	X X	х х х х	X X	
FORD COUNTY JAIL*	1931	38	12	7	 (1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No exercise area.** (4) Does not comply with State Fire Marshal's regulations.** 	Х	X X	Х	

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.

** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 18 -

PRIORITY OF CORRECTIVE ACTION DATE CONSTRUCTED CAPACITY NAME OF FACILITY DEFICIENCIES FORD COUNTY (5) Does not provide adequate separation of Χ JAIL (Continued) prisoners.** (6) Electrical fixtures are within prisoners χ Inadequate lighting in cell block areas.** No emergency electrical power.**
Inadequate ventilation.** χ No standard inmate clothing issued.** Painted surfaces need repainting.** Overall sanitation needs to be improved.** Does not provide adequate containers in the cell block areas for disposal of solid waste.** (14) Three meals per day, or the equivalent, are not provided.** FRANKLIN COUNTY 1972 30 30 8 (1) Inadequate administrative space.**(2) Drop cords accessible to prisoners.** JAIL GEARY COUNTY 1951 24 24 Inadequate administrative space.** Cell areas do not maintain 52 sq. ft. per JAIL* prisoner.** No exercise area.** Does not comply with State Fire Marshal's

regulations.**

(5) Inadequate lighting in cel(6) Inadequate ventilation.**

Inadequate lighting in cell block areas.**

Χ

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available. ** This deficiency existed in previous inspection reports but no corrective action has been taken.

PRIORITY OF CORRECTIVE DATE CONSTRUCTED CAPACITY **DEFICIENCIES** NAME OF FACILITY GEARY COUNTY (7) No standard inmate clothing issued.** JAIL (Continued) (1) Cell areas do not maintain 52 sq. ft. per GRAHAM COUNTY 1958 16 8 1 prisoner.** JAIL No security or insect screens on windows.** No exercise area. No emergency electrical power. Χ No shower facility provided for one cell area. Three meals per day, or the equivalent, are Χ not provided.** GRANT COUNTY 1970 28 22 2 (1) Cell areas do not maintain 52 sq. ft. per prisoner.** JAIL No intercom system between jail office and Χ cell block areas.** Overall sanitation needs to be improved. (1) Does not comply with State Fire Marshal's GREENWOOD COUNTY 1955 11 11 7 χ JAIL* regulations. Cell areas do not maintain 52 sq. ft. per HARVEY COUNTY 1965 43 31 15 prisoner.**
(2) No exercise area.** JAIL*

- 20 -

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

			A	ILY N			PRIORITY OF CORRECTIVE ACTION		
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE	
HARVEY COUNTY JAIL (Continued)					(3) Does not comply with State Fire Marshal's regulations.** (4) Electrical wires accessible to prisoners.** (5) Inadequate lighting in cell block areas. (6) Drop cords accessible to prisoners.** (7) No intercom system between jail office and cell block areas.** (8) Inadequate plumbing.** (9) Painted surfaces need repainting.** (10) No standard inmate clothing issued.** (11) Does not provide sufficient bedding. (12) Three meals per day, or the equivalent, are not provided.** (13) Plate glass accessible to prisoners in security area.** (14) Does not provide sufficient personnel for efficient operation.**	X X X	х х х	X X X	
HODGEMAN COUNTY JAIL*	1927	9	5	1	 (1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No security or insect screens on windows.** (4) No floor drains in cell block areas.** (5) No exercise area.** (6) Does not comply with State Fire Marshal's regulations.** (7) Does not provide adequate separation of prisoners.** 	Х	X X X	X X	

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 21 -

	Ð		6	AILY ON		COF	ORITY RRECTIV ACTION	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
HODGEMAN COUNTY JAIL (Continued)					(8) Inadequate lighting in cell block areas.** (9) Electrical fixtures are within prisoners reach.** (10) Inadequate plumbing.**	Х	X	
					 (11) Inadequate ventilation.** (12) No standard inmate clothing issued.** (13) Overall sanitation needs to be improved.** (14) Does not provide sufficient bedding.** (15) Painted surfaces needs repainting.** (16) No 30 day menu provided.** (17) Bunks not securely fastened to wall or floor.** (18) No written policies, procedures, or regulations for a safe and secure operation.** 	Х	X X	X X X X
JACKSON COUNTY JAIL*	1929	15	6	6	(1) Inadequate administrative space.* (2) Cell areas do not maintain 52 sq. ft. per prisoner.**		X X	
					(3) No security or insect screens on windows.** (4) Stairway will not accommodate an ambulance cot.** (5) No floor drains in cell block areas.** (6) Bunks not securely fastened to wall or floor.** (7) Does not comply with State Fire Marshal's	X	X	Х
					regulations.** (8) Electrical fixtures are within prisoners reach.** (9) Inadequate lighting in cell block areas.**	X	Х	

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 22 -

PRIORITY OF CORRECTIVE AVERAGE DAILY POPULATION ACTION DATE CONSTRUCTED CAPACITY NAME OF FACILITY DEFICIENCIES JACKSON COUNTY (10) Inadequate ventilation.** JAIL (Continued) Inadequate plumbing.** Security equipment is in need of repair.

Does not provide two sets of keys for security area.** (14) No standard inmate clothing issued.** JEFFERSON COUNTY 1933 20 (1) Does not comply with State Fire Marshal's JAIL* regulations.** Inadequate ventilation.** Inadequate plumbing.** Painted surfaces need repainting.** JEWELL COUNTY 1889 (1) Inadequate administrative space.** JAIL* (2) Cell areas do not maintain 52 sq. ft. per prisoner.** No security or insect screens on windows.** Stairway will not accommodate an ambulance cot.** No floor drains in cell block areas.** No exercise area.** Does not comply with State Fire Marshal's regulations.** Electrical wiring does not meet State Fire Marshal's regulations.** (9) Inadequate lighting in cell block areas.**

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	Ð		e e	VILY NO		COF	ORITY RRECTIV ACTION	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
JEWELL COUNTY JAIL (Continued)					 (10) Inadequate exterior lighting.** (11) Inadequate ventilation.** (12) Inadequate plumbing.** (13) Painted surfaces need repainting. (14) Security equipment is in need of repair.** (15) No around-the-clock awake and alert supervision. (16) Does not provide adequate separation of prisoners.** 	X X	X X	X
KEARNY COUNTY JAIL	1963	15	15	4	 (1) Inadequate administrative space.** (2) No security screens on windows.** (3) No exercise area.** (4) No emergency electrical power.** (5) No intercom system between jail office and cell block areas.** (6) Does not provide adequate containers in the cell block areas for disposal of solid waste. 		X X X X	X X
KINGMAN COUNTY JAIL*	1969	16	8	1	 (1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No exercise area.** (4) Does not comply with State Fire Marshal's regulations.** (5) No emergency electrical power.** 	X	X X	Х

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 24 -

			А	AILY ON		PRI(CO l		
NAME OF FACILITY	DATE	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
KINGMAN COUNTY JAIL (Continued)					 (6) No intercom system between jail office and cell block areas.** (7) Inadequate ventilation.** (8) Plumbing fixtures accessible to prisoners in cell block areas.** (9) No around-the-clock awake and alert supervision. (10) No visual supervision of prisoners at least every 60 minutes. (11) Does not provide adequate separation of prisoners.** 	X X	X X X	
LABETTE COUNTY JAIL*	1954	32	24	16	 (1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No insect screens on windows.** (4) No floor drains in cell block areas.** (5) No exercise area.** (6) Does not provide bunks, tables and benches in dormitory areas.** (7) No holding cell for the purpose of processing prisoners.** (8) Bunks not securely fastened to wall or floor.** (9) Does not comply with State Fire Marshal's regulations. (10) Drop cords accessible to prisoners.** (11) Electrical fixtures are within prisoners reach. 	X X X	X X X	X X X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	Q	Q	VILY NO		PRIORITY OF CORRECTIVE ACTION			
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
LABETTE COUNTY JAIL (Continued)					(12) Inadequate lighting in cell block areas.** (13) Inadequate exterior lighting.** (14) No emergency electrical power.** (15) No intercom system between jail office and cell block areas.** (16) Inadequate ventilation.** (17) Heating units inadequate to maintain a minimum of 68 degrees.** (18) Plumbing fixtures are not of the type designed for jail use.** (19) No standard inmate clothing issued.** (20) Inadequate plumbing.** (21) Overall sanitation needs to be improved.** (22) No written security procedures.** (23) No written emergency procedures.** (24) Inadequate storage of tools.** (25) Security equipment is in need of repair.** (26) Inadequate housing to permit effective management of special problem prisoners.** (27) Does not provide adequate separation of prisoners.** (28) Window glass accessible to prisoners.** (29) No written policies, procedures, or regulations for a safe and secure operation.** (30) No written rules for prisoners.** (31) No written disciplinary procedures.	X X	x x x x x	X X X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 26 -

	0		a	AILY ON		COF	ORITY RRECTIV	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
LANE COUNTY JAIL*	1935	8	8	1	(1) Plumbing fixtures are not of the type designed for jail use.** (2) No shower facility provided in two-man cell.** (3) No standard inmate clothing issued.**		Х	X X
LINN COUNTY JAIL*	1907	13	7	1	(1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No security screens on windows.** (4) Stairway will not accommodate an ambulance cot.** (5) No floor drains in cell block areas.** (6) No exercise area.** (7) Bunks not securely fastened to wall or floor.** (8) Does not comply with State Fire Marshal's regulations.** (9) Electrical wiring does not meet State Fire Marshal's regulations.** (10) Electrical fixtures are within prisoners reach.** (11) Inadequate lighting in cell block areas.** (12) Inadequate exterior lighting.** (13) No intercom system between jail office and cell block areas.** (14) Inadequate ventilation.** (15) Plumbing fixtures are not of the type designed for jail use.**	X X X	X X X X	X X X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 27 -

	A		6	AILY NO			PRIORITY OF CORRECTIVE ACTION		
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE	
LINN COUNTY JAIL (Continued)					(16) No standard inmate clothing issued.** (17) No written security procedures.** (18) No written emergency procedures.** (19) No written policies, procedures, or regulations for a safe and secure operation.** (20) No written rules for prisoners.** (21) No written disciplinary procedures.**	X X	Х	X X X	
McPHERSON COUNTY JAIL	1958	27	27	14	 (1) Inadequate administrative space.** (2) No exercise area.** (3) Drop cords and extension cords accessible to prisoners.** (4) Does not provide sufficient personnel for efficient operation.** 	X X	Х	Х	
MARION COUNTY JAIL*	1937	21	14	2	 (1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No floor drains in cell block areas.** (4) No exercise area.** (5) Does not comply with State Fire Marshal's regulations.** (6) No intercom system between jail office and cell block areas.** (7) Inadequate ventilation.** (8) Inadequate plumbing.** 	Χ	X X X	X X	

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	æ		A	AILY ON		COF	ORITY RRECTIV ACTION	OF √E
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
MARION COUNTY JAIL (Continued)					(9) No standard inmate clothing issued.** (10) Painted surfaces need repainting.** (11) No around-the-clock awake and alert supervision.** (12) No written emergency procedures.** (13) No written policies, procedures, or regulations for a safe and secure operation.** (14) No written rules for prisoners.**	X X X		X X
MEADE COUNTY JAIL*	1933	8	8	1	 (1) Inadequate administrative space.** (2) No exercise area.** (3) Does not comply with State Fire Marshal's regulations.** (4) Inadequate ventilation.** (5) Plumbing fixtures are not of the type designed for jail use.** (6) No standard inmate clothing issued.** (7) No visual supervision of prisoners at least every 60 minutes.** (8) Wooden bunks being used.** (9) Bunks not securely fastened to wall or floor.** 	X X	X X X	X X
MIAMI COUNTY JAIL	1967	26	26	12	(1) No insect screens on windows.** (2) No exercise area.** (3) No intercom system between jail office and cell block areas.**		X X	Х

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available. ** This deficiency existed in previous inspection reports but no corrective action has been taken.

	А		Gi .	AILY ON		COF	ORITY RRECTIV	
NAME OF FACILITY	DATE	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
MIAMI COUNTY JAIL (Continued)					(4) Inadequate plumbing.**		Х	
MITCHELL COUNTY JAIL	1959	12	12	1	 (1) Electrical fixtures are within prisoners reach.** (2) No emergency electrical power.** (3) Does not provide adequate separation of prisoners.** 	X	X X	
MONTGOMERY COUNTY JAIL*	1931	61	27	20	 (1) Cell areas do not maintain 52 sq. ft. per prisoner.** (2) Security equipment is in need of repair.** (3) Work tables and counter top surfaces are checked and cracked.** (4) Window glass accessible to prisoners.** 	Х	X X	Χ
MORRIS COUNTY JAIL*	1969	8	8	1	 (1) Inadequate administrative space.** (2) No exercise area.** (3) Does not comply with State Fire Marshal's regulations. (4) Does not provide adequate separation of prisoners.** (5) Inadequate lighting in cell block areas. (6) No intercom system between jail office and cell block areas.** (7) Heating units inadequate to maintain a minimum of 68 degrees. 	X	X X X	Х


^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 30 -

PRIORITY OF CORRECTIVE AVERAGE DAILY POPULATION ACTION RECOMMENDED CAPACITY DATE CONSTRUCTED CAPACITY NAME OF FACILITY DEFICIENCIES MORRIS COUNTY Inadequate ventilation. JAIL (Continued) Security equipment is in need of repair. No standard inmate clothing issued. Overall sanitation needs to be improved. Painted surfaces needs repainting. Three meals per day, or the equivalent, are Χ not provided. No 30 day menu provided. No written emergency procedures.** (16) No written policies, procedures, or regulations for a safe and secure operation.** MORTON COUNTY 1964 9 3 Inadequate administrative space.** Cell areas do not maintain 52 sq. ft. per JAIL prisoner.** No security or insect screens on windows.** No exercise area.** No emergency electrical power. No intercom system between jail office and cell block areas.** No standard inmate clothing issued.** Overall sanitation needs to be improved.

No written emergency procedures.**

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.



NAME OF FACILITY NAME OF FACILITY 1948 22 12 6 (1) Inadequate administrative space.**		e.	6	NILY ON		PRIORITY OF CORRECTIVE ACTION				
JAIL* (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No security or insect screens on windows.** (4) No floor drains in cell block areas.** (5) No exercise area.** (6) Does not comply with State Fire Marshal's xregulations.** (7) Electrical fixtures are within prisoners xreach.** (8) No emergency electrical power.** (9) No intercom system between jail office and cell block areas.** (10) Inadequate ventilation.** (11) No standard inmate clothing issued.** (12) Does not provide sufficient bedding.** (13) Does not provide sufficient bedding.** (14) Three meals per day, or the equivalent, are not provided.** (15) No 30 day menu provided.** (15) No 30 day menu provided.** (16) No around-the-clock awake and alert super- xreach.** (17) Does not provide adequate separation of	NAME OF FACILITY	DATE	CAPACITY	RECOMMENDS CAPACITY	AVERAGE DA POPULATIO	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE	
		1948	22	12	6	(2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No security or insect screens on windows.** (4) No floor drains in cell block areas.** (5) No exercise area.** (6) Does not comply with State Fire Marshal's regulations.** (7) Electrical fixtures are within prisoners reach.** (8) No emergency electrical power.** (9) No intercom system between jail office and cell block areas.** (10) Inadequate ventilation.** (11) No standard inmate clothing issued.** (12) Does not provide sufficient bedding.** (13) Does not provide effective pest control program.** (14) Three meals per day, or the equivalent, are not provided.** (15) No 30 day menu provided.** (16) No around-the-clock awake and alert supervision.** (17) Does not provide adequate separation of	Х	X X X X	X X	

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available. ** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 32 -

	Ð	Ð	N N		PRIORITY OF CORRECTIVE ACTION			
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
NESS COUNTY JAIL	1955	6	6	1	(1) No security screens on windows.**		Х	
NORTON COUNTY JAIL*	1929	7	4	4	 (1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No security or insect screens on windows.** (4) No exercise area.** (5) Stairway will not accommodate an ambulance cot.** (6) Does not provide adequate separation of prisoners.** (7) Does not comply with State Fire Marshal's regulations.** (8) Bunks and tables not securely fastened to wall or floor.** (9) Electrical fixtures are within prisoners reach.** (10) Plumbing fixtures are not of the type designed for jail use.** (11) Inadequate lighting in cell block areas. (12) Inadequate ventilation. (13) Heating units inadequate to maintain a minimum of 68 degrees. (14) Inadequate plumbing. (15) Overall sanitation needs to be improved.** (16) Does not provide effective pest control program.** 	X X	X X X X X X	XXX

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.

** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 33 -

NAME OF FACILITY	DATE CONSTRUCTED CAPACITY		RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	PRIORITY OF CORRECTIVE ACTION		
		CAPACITY				URGENT	NECESSARY	DESIRABLE
NORTON COUNTY JAIL (Continued)					(17) No standard inmate clothing issued.** (18) Does not provide sufficient bedding.** (19) Inadequate food preparation area. (20) Inadequate storage for cleaning equipment.			X X X X
OSAGE COUNTY JAIL*	1922	7	7	1	 Inadequate administrative space.** No floor drains in cell block areas.** No exercise area.** Does not comply with State Fire Marshal's regulations. No emergency electrical power.** No intercom system between jail office and cell block areas.** Inadequate ventilation.** No standard inmate clothing issued.** Does not provide effective pest control program. No visual supervision of prisoners at least every 60 minutes. Steam heat radiators accessible to prisoners.** No around-the-clock awake and alert supervision. Does not provide adequate separation of prisoners.** 	X X	X X X X	X X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.

** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 34 -

	a l		E.	VILY ON		PRIORITY OF CORRECTIVE ACTION		
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
OSBORNE COUNTY JAII.	1956	12	6	1.5	 (1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No exercise area.** (4) No emergency electrical power.** (5) Inadequate lighting in cell block areas. (6) Overall sanitation needs to be improved. (7) Does not provide adequate containers in the cell block areas for disposal of solid waste. 		X X X	X X X
OTTAWA COUNTY JAIL*	1915	5	5	3	 (1) Inadequate administrative space.** (2) No security screens on windows.** (3) No exercise area.** (4) Tables and benches not securely fastened to wall or floor.** (5) Does not comply with State Fire Marshal's regulations.** (6) Electrical fixtures are within prisoners reach.** (7) No emergency electrical power.** (8) Inadequate ventilation.** (9) Plumbing fixtures are not of the type designed for jail use.** (10) Kitchen and laundry equipment not provided by local government. (11) Does not provide two sets of keys for security area.** 	X X	X X X X	X

- 35 -

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available. ** This deficiency existed in previous inspection reports but no corrective action has been taken.

PRIORITY OF CORRECTIVE ACTION

	O.	1	Ð	VILY N		PRIORITY OF CORRECTIVE ACTION		
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
PAWNEE COUNTY JAIL	1952	11	11	5	(1) No around-the-clock awake and alert super- vision.**	Х		
POTTAWATOMIE COUNTY JAIL	1970	16	16	5	 (1) No exercise area.** (2) Drop cords accessible to prisoners.** (3) Electrical fixtures are within prisoners reach. (4) No standard inmate clothing issued.** (5) Painted surfaces need repainting.** (6) Three meals per day, or the equivalent, are not provided.** (7) Does not provide adequate separation of prisoners.** 	X X	X X	X X X
REPUBLIC COUNTY* JAIL	1939	14	14	1	 (1) Inadequate administrative space.** (2) No insect screens on windows.** (3) Bunks not securely fastened to wall or floor. (4) Does not comply with State Fire Marshal's regulations. (5) Electrical fixtures are within prisoners reach.** (6) Inadequate ventilation. (7) No written security procedures.** (8) No written emergency procedures.** (9) No key control.** (10) Security equipment is in need of repair.** 	X X X	X X X X	

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 36 -

	æ		А	AILY ON		CO	ORITY RRECTIV ACTION	/E
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
REPUBLIC COUNTY JAIL (Continued)					 (11) Does not provide adequate separation of prisoners.** (12) Steam heat radiators accessible to the prisoners. (13) No around-the-clock awake and alert supervision.** (14) No written policies, procedures, or regulations for a safe and secure operation.** 	X X	X X	
RICE COUNTY JAIL*	1929	27	11	3	 (1) Cell areas do not maintain 52 sq. ft. per prisoner.** (2) No security screens on windows.** (3) No floor drains in cell block areas.** (4) No exercise area.** (5) Does not comply with State Fire Marshal's regulations.** (6) Drop cords accessible to prisoners.** (7) Electrical fixtures are within prisoners reach.** (8) Inadequate lighting in cell block areas.** (9) No emergency electrical power.** (10) No intercom system between jail office and cell block areas.** (11) Inadequate ventilation.** (12) No standard inmate clothing issued.** (13) No 30 day menu provided.** (14) No visual supervision of prisoners at least every 60 minutes.** 	X X X	X X X X	X X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 37 -

NAME OF FACILITY	Œ		А	AILY N		COF	ORITY RRECTIV	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
RICE COUNTY JAIL (Continued)					 (15) Window glass accessible to prisoners.** (16) Benches not securely fastened to wall or floor.** (17) No around-the-clock awake and alert supervision.** (18) No written policies, procedures, or regulations for a safe and secure operation.** (19) No written rules for prisoners.** (20) No written disciplinary procedures.** (21) No written emergency procedures.** 	x x x	X X	X X
ROOKS COUNTY JAIL	1930	11	11	1	 (1) No insect screens on windows.** (2) No emergency electrical power.** (3) No intercom system between jail office and cell block areas.** (4) One bunk not securely fastened to wall or floor. (5) No written security procedures.** (6) No written rules for prisoners.** (7) No written disciplinary procedures.** 		X X X X	X X
RUSSELL COUNTY JAIL	1956	25	13	6	(1) Cell areas do not maintain 52 sq. ft. per prisoner.** (2) No exercise area.** (3) No emergency electrical power.** (4) Inadequate lighting in cell block areas.**		X X X	Х

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 38 -

NAME OF FACILITY	А		Æ	AILY ON		COF	ORITY RRECTIV ACTION	-
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
SALINE COUNTY JAIL*	1962	131	59	55	(1) Inadequate administrative space.** (2) No exercise area.** (3) Dormitories exceed recommended capacity.** (4) Does not comply with State Fire Marshal's regulations.**	Х	X X	Х
SCOTT COUNTY JAIL	1940	17	6	5	 Inadequate administrative space.** Cell areas do not maintain 52 sq. ft. per prisoner.** No insect or security screens on windows.** Electrical fixtures are within prisoners reach.** No emergency electrical power.** Overall sanitation needs to be improved.** Painted surfaces needs repainting.** Inadequate storage for cleaning equipment.** No around-the-clock awake and alert supervision.** No visual supervision of prisoners at least every 60 minutes.** 	X X X	X X X	X X X
SEDGWICK COUNTY JAIL*	1958	225	135	140	 (1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) Does not comply with State Fire Marshal's regulations.** 	Х	X X	

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.

** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 39 ~

	6		a	AILY ON		COF	ORITY RRECTIV ACTION	٧E
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
SEDGWICK COUNTY JAIL (Continued)					 (4) Drop cords accessible to prisoners.** (5) Electrical fixtures are within prisoners reach.** (6) Inadequate ventilation.** (7) Does not provide adequate clothing exchange.** (8) Does not provide adequate bedding exchange.** (9) Overall sanitation needs to be improved.** (10) Inadequate plumbing.** (11) Inadequate housing to permit effective management of special problem prisoners.** 	X X	X X X	X X X
SEWARD COUNTY JAIL*	1958	42	23	12	(1) Cell areas do not maintain 52 sq. ft. per prisoner.** (2) Inadequate ventilation.** (3) No emergency electrical power.** (4) No intercom system between jail office and cell block areas.** (5) Inadequate lighting in cell block areas.** (6) No standard inmate clothing issued.** (7) Overall sanitation needs to be improved.** (8) Painted surfaces needs repainting.**		X X X X	X X X
SHAWNEE COUNTY JAIL*	1965	103	60	105	(1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) Dormitories exceed recommended capacity.**		X X X	

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	<u> </u>		a	AILY ON		COF	ORITY RRECTIV	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
SHAWNEE COUNTY JAIL (Continued)					 (4) Drop cords accessible to prisoners.** (5) Inadequate lighting in cell block areas.** (6) Painted surfaces need repainting.** (7) Overall sanitation needs to be improved.** (8) Inadequate housing to permit effective management of special problem prisoners.** (9) Does not provide sufficient personnel for efficient operation.** 	X X	X X	X X
SMITH COUNTY JAIL	1976	9	9	3	(1) No exercise area. (2) No emergency electrical power.		Х	Х
STANTON COUNTY JAIL*	1925	9	5	1.5	 (1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) No exercise area.** (4) Does not provide adequate separation of prisoners.** (5) Does not comply with State Fire Marshal's 	X	X X	Х
					regulations.** (6) Bunks not securely fastened to wall or floor.** (7) No emergency electrical power.** (8) Electrical fixtures are within prisoners reach.** (9) Inadequate lighting in cell block areas.** (10) Inadequate exterior lighting.**	Х	X X	Χ

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	Œ		G	AILY ON		COF	ORITY RRECTIN	
NAME OF FACILITY	DATE	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
STANTON COUNTY JAIL (Continued)					(11) Inadequate ventilation.** (12) Inadequate plumbing.** (13) Overall sanitation needs to be improved.** (14) No standard inmate clothing issued.** (15) Three meals per day, or the equivalent, are not provided.** (16) No 30 day menu provided.** (17) Work tables and counter top surfaces are checked and cracked. (18) No dining area for prisoners. (19) No written emergency procedures.**	X	X X	X X X X
STEVENS COUNTY JAIL	1958	12	12	2	(1) No exercise area. (2) No intercom system between jail office and cell block areas.** (3) No emergency electrical power. (4) No standard inmate clothing issued. (5) No 30 day menu provided. (6) No written emergency procedures.	Х	X X X	X X
SUMNER COUNTY JAIL*	1954	31	18	25	(1) Cell areas do not maintain 52 sq. ft. per prisoner.** (2) No insect screens on windows.** (3) No floor drains in cell block areas.** (4) No exercise area.** (5) Does not comply with State Fire Marshal's regulations.**	Х	X X	X X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	Ð		A	AILY ON		COF	ORITY RRECTIV	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
SUMNER COUNTY JAIL (Continued)					 (6) Drop cords accessible to prisoners.** (7) Electrical fixtures are within prisoners reach.** (8) No emergency electrical power.** (9) Inadequate ventilation.** (10) Painted surfaces need repainting.** 	X X	X X	Χ
WABAUNSEE COUNTY JAIL	1900	18	18	1	 (1) Inadequate administrative space.** (2) No insect screens on windows.** (3) No emergency electrical power.** (4) No intercom system between jail office and cell block areas.** (5) Inadequate ventilation.** (6) Does not provide adequate separation of prisoners.** 		X X X X	
WASHINGTON COUNTY JAIL*	1900	6	6	7	 (1) Inadequate administrative space.** (2) Bunks, tables and benches not securely fastened to wall or floor.** (3) Does not comply with State Fire Marshal's regulations.** (4) Electrical fixtures are within prisoners reach.** (5) No emergency electrical power.** (6) No intercom system between jail office and cell block areas.** 	X X	X X X	

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.

** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 43 -

	-D		A	AILY ON		COF	ORITY RRECTIV ACTION	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
WASHINGTON COUNTY JAIL (Continued)					 (7) Inadequate ventilation.** (8) Drop cords accessible to prisoners.** (9) No standard inmate clothing issued.** (10) No written security procedures.** (11) No written emergency procedures.** (12) Does not provide adequate separation of prisoners.** (13) No around-the-clock awake and alert supervision.** (14) No written policies, procedures, or regulations for a safe and secure operation.** 	X X X	X X X	Х
WILSON COUNTY JAIL	1976	14	14	1	 (1) No standard inmate clothing issued.** (2) No around-the-clock awake and alert supervision.** (3) No visual supervision of prisoners at least every 60 minutes.** 	X X		Х
WYANDOTTE COUNTY JAIL*	1927	162	58	71	 (1) Cell block areas do not maintain 52 sq. ft. per prisoner.** (2) No insect screens on windows.** (3) No exercise area.** (4) Does not comply with State Fire Marshal's regulations.** (5) Inadequate ventilation.** 	Χ	X X X	X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

	e.		A	VILY ON		COF	ORITY RRECTIV	
NAME OF FACILITY	DATE	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
WYANDOTTE COUNTY JAIL (Continued)					(6) Kitchen equipment not sanitized consistent with Public Health Standards.** (7) Painted surfaces need repainting. (8) Overall sanitation needs to be improved. (9) Does not provide adequate containers in the cell block areas for disposal of solid waste.**		Х	X X X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

DEFICIENCIES BY COUNTY (LOCKUPS) - 46 -

	Ð		A	NI V		COF	ORITY RRECTIV	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
HORTON CITY LOCKUP* (Brown County)	1914				 (1) No security or insect screens on windows.** (2) Electrical fixtures are within prisoners reach.** (3) Inadequate exterior lighting.** (4) Does not comply with State Fire Marshal's regulations.** (5) No emergency electrical power.** (6) No intercom system between jail office and cell block areas.** (7) Inadequate ventilation.** (8) No standard inmate clothing issued.** (9) Painted surfaces need repainting.** 	X	X X X	X X
AUGUSTA CITY LOCKUP* (Butler County)	Early 1920's	8	3	1	 (1) Inadequate administrative space.** (2) Cell areas do not maintain 52 sq. ft. per prisoner.** (3) Does not comply with State Fire Marshal's regulations.** (4) No insect screens on windows.** (5) Inadequate lighting in cell block areas.** (6) No intercom system between jail office and cell block areas.** (7) Inadequate ventilation.** (8) Inadequate plumbing.** 	X	X X X X X	

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.

** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 47 -

	Ð		A	AILY ON		COF	ORITY RRECTIV ACTION	
NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
BAXTER SPRINGS CITY LOCKUP (Cherokee County)	1926	4	4	1	 Inadequate administrative space.** No insect screens on windows.** Electrical fixtures are within prisoners. reach.** No intercom system between jail office and cell block areas.** Inadequate ventilation.** Plumbing fixtures accessible to prisoners in cell block areas.** No standard inmate clothing issued.** Overall sanitation needs to be improved. No visual supervision of prisoners at least every 60 minutes. No around-the-clock awake and alert supervision. 	X X	X X X X	X X
COLUMBUS CITY LOCKUP (Cherokee County)	1924	5	5	1	 (1) Inadequate administrative space.** (2) No floor drains in cell block areas.** (3) No intercom system between jail office and cell block areas.** (4) Inadequate ventilation.** (5) Plumbing fixtures are not of the type designed for jail use.** (6) Plumbing fixtures accessible to prisoners in cell block areas.** (7) No standard inmate clothing issued.** (8) No around-the-clock awake and alert super-vision. 	X	X X X X	X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 48 -

CONTINUED 10F2

THE REPORT OF THE CASE OF THE

	А		A	AILY NO		COF	ORITY RRECTIV ACTION	
NAME OF FACILITY	DATE	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	URGENT	NECESSARY	DESIRABLE
COLUMBUS CITY LOCKUP (Continued)					(9) No visual supervision of prisoners at least every 60 minutes.	Х	400	
PITTSBURG CITY LOCKUP (Crawford County)	1962	3	3	1	 (1) Cell areas do not maintain 52 sq. ft. per prisoner.** (2) No security screens on windows.** (3) Inadequate lighting in cell block areas.** (4) No emergency electrical power.** (5) No standard inmate clothing issued.** 		X X X	Х
PARSONS CITY LOCKUP (Labette County)	1937	6	6	1	 (1) Inadequate administrative space.** (2) No insect screens on windows.** (3) No floor drains in cell block areas.** (4) Inadequate lighting in cell block areas.** (5) Light fixtures (controls) within prisoners reach.** (6) No intercom system between jail office and cell block areas.** (7) Heating units inadequate to maintain a minimum of 68 degrees.** (8) Inadequate ventilation.** (9) No standard inmate clothing issued.** (10) Does not provide adequate separation of prisoners.** (11) Window glass accessible to prisoners.** 	Х	X X X X	X

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available. ** This deficiency existed in previous inspection reports but no corrective action has been taken.

- 49 -

PRIORITY OF CORRECTIVE ACTION DATE CONSTRUCTED RECOMMENDED CAPACITY CAPACITY NAME OF FACILITY DEFICIENCIES OAKLEY CITY 1949 Inadequate administrative space.** LOCKUP* Cell areas do not maintain 52 sq. ft. per (Logan County) prisoner.** No floor drains in cell block areas.** No exercise area. Does not comply with State Fire Marshal's regulations.** Wooden tables being used in cell block areas. No holding cell for the purpose of processing prisoners. Does not provide adequate separation of prisoners. Inadequate lighting in cell block areas. No emergency electrical power.** (11) No intercom system between jail office and cell block areas.** (12) Inadequate plumbing.** (13) Three meals per day, or the equivalent, are not provided. (14) No written emergency procedures.** CHANUTE CITY 1925 6 No security screens on windows.** LOCKUP* No immediate access to shower.** (Neosho County) Does not comply with State Fire Marshal's regulations.** Inadequate ventilation.** No standard inmate clothing issued **

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available. ** This deficiency existed in previous inspection reports but no corrective action has been taken.

NAME OF FACILITY	DATE CONSTRUCTED	CAPACITY	RECOMMENDED CAPACITY	AVERAGE DAILY POPULATION	DEFICIENCIES	PRIORITY OF CORRECTIVE ACTION		
						URGENT	NECESSARY	DESIRABLE
CHANUTE CITY LOCKUP (Continued)					(6) Steam heat radiators accessible to prisoners.(7) Window glass accessible to prisoners.**		X X	
RUSSELL CITY LOCKUP* (Russell County)	1969	4	2	1	 (1) Cell areas do not maintain 52 sq. ft. per prisoner.** (2) Does not comply with State Fire Marshal's regulations.** (3) No floor drains in cell block areas.** (4) Inadequate lighting in cell block areas.** (5) No emergency electrical power. (6) Does not provide adequate bedding exchange. 	Х	X X X	X X

- 51 .

^{*} Reports from either the State Fire Marshal's Office or the State Department of Health and Environment are available.
** This deficiency existed in previous inspection reports but no corrective action has been taken.

SUMMARY

The mission of the Jail Inspection Section is to upgrade the jail/detention facilities operated by the cities and counties within the state via maintenance of a uniform set of standards for sanitation and the care and safety of inmates. The Department of Corrections, pursuant to K.S.A. 75-5228, is responsible for providing staff training, technical assistance and leadership in areas related to the upgrading of the conditions of the jails and detention facilities within the State of Kansas.

The Kansas Advisory Jail Standards and Procedures have been developed to assist Administrators in their efforts to upgrade their detention facilities. These are state standards which are applied by the Jail Inspectors during an inspection. Recommendations for the improvement of such areas are made in report form to the District Judges, County Commissioners and County Attorneys following the inspection.

The effectiveness of jail standards is measured by the reduction of the number of deficiencies and by the increase of the total number of facilities which currently meet the standards. It should be noted that cooperation of the local units of government across the state has been outstanding. Without the continued cooperation of these various units of government, the implementation of the Kansas Advisory Jail Standards and Procedures can not be successful.

END